



DEPARTMENT OF THE ARMY
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1741 MARSHALL ROAD
FORT BLISS, TX 79916

ENTERED

RECEIVED

DEC 18 2014

December 12, 2014

NMED
Hazardous Waste Bureau

Environmental Division

Mr. David Cobrain
Project Leader
New Mexico Environmental Department-HWB
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303


Dear Mr. Cobrain:

On June 19, 2014, the Directorate of Public Works, Environmental Division conducted the annual Post-Closure Site inspection of the Dona Ana Range Camp Sanitary Landfill, Solid Waste Management Unit (SWMU) No. 27/FTBL-012 as per NMED letter dated October 30, 2007. The correspondence indicated the inspections shall be performed before and after the wet season and after each major rainfall event that produces more than one inch of rain. Site inspection must include observations of the final cover and side slopes, the surface water drainage system and vegetative cover. An inspection report must be submitted and include photographs and descriptions of the site to NMED annually.

During the inspection of the SWMU-27/FTBL-012 landfill on June 19, 2014, the native vegetative, fence, and signage were found to be in very good condition. The landfill cover and slopes showed no evidence of erosion.

If you have any questions concerning this report, please do not hesitate to contact Isaac Trejo, at 915-568-1153, isaac.trejo@us.army.mil.

Sincerely,


Sylvia A. Waggoner
Chief, Compliance Branch
Directorate of Public Works

Enclosures



**DERA Sites
FTBL-012**

**Dona Ana Range Camp
Rubble LandFill
Fort Bliss, NM**




GPS Points - 5 Sept/10 Oct 2014

● Fence Post

---- Road Centerline

— Fence Line: As-Built



SCALE 1:4,000

IMAGERY SOURCE: USGS 2008

Map Location



Dona Range Camp Rubble Landfill Inspection
SWMU-27/FTBL-012

Unit: IMBW- PWE

Inspection Date: 06-19-2014

Facility ID: SWMU-27/FTBL-012

Facility Name: Dona Ana Range Camp Rubble Landfill #12

Assessor: Ron Baca

Telephone Number: (915) 568-7979

Email Address: ronald.h.baca.ctr@mail.mil

List of Observations:

1. Observation: There was no erosion detected on the cap or on the perimeter of the landfill.
2. Observation: Vegetation is very healthy on the surrounding area of the landfill and on the final cover.
3. Observation: Signage and fences were in good condition.

Observations #1 & 2	
<p>Observation: Looking north across the SWMU- 27 / FTBL-012 landfill. No erosion on the landfill cap.</p>	
<p>Note: Vegetation on landfill cap.</p>	

**Dona Range Camp Rubble Landfill Inspection
SWMU-27/FTBL-012**

Observation #1 & 2	
<p>Observation: Looking northeast at arroyo on the east side of SWMU-27 / FTBL-012 landfill. There is no erosion present.</p> <p>Note: Vegetation on landfill cap.</p>	

Observation #1 & 2	
<p>Observation: Looking west across the SWMU-27 / FTBL-012 landfill. No erosion on the landfill cap.</p> <p>Note: Vegetation on landfill cap.</p>	

Dona Range Camp Rubble Landfill Inspection
SWMU-27/FTBL-012

<p>Observation #1</p>	
<p>Observation: Looking south at the swell on the west side of SWMU-27 / FTBL-012 landfill. No erosion in or around swell.</p> <p><u>Note: Swell is in very good condition</u></p>	

<p>Observation #2</p>	
<p>Observation: Looking southwest across the SWMU-27 / FTBL-012 landfill. Vegetation is very healthy on the surrounding area of the landfill and on the final cover.</p>	

**Dona Range Camp Rubble Landfill Inspection
SWMU-27/FTBL-012**

Observation #3	
<p>Observation: Looking northwest at locked gate and fence line of SWMU-27 / FTBL-012 landfill.</p> <p>Note: The chain, lock and gate are in good condition.</p>	 <p>A wide-angle photograph showing a dirt road leading to a closed gate in a desert environment. The gate is made of chain-link fencing and is flanked by concrete pillars. In the background, there are low mountains under a blue sky with scattered clouds. A red timestamp '15 14 01' is visible in the bottom right corner of the photo.</p>

Observation #3	
<p>Observation: Looking west at signage on fence line of SWMU-27 / FTBL-012 landfill.</p> <p>Note: Signage and fence line are in good condition.</p>	 <p>A photograph of a signpost on a dirt path. The signpost has two rectangular signs. The top sign is white with black text that reads 'RESTRICTED AREA'. The bottom sign is white with black text that reads 'ENTRADA PROHIBIDA'. The signpost is surrounded by desert vegetation. In the background, a large pile of rubble is visible. A red timestamp '19 13 59' is visible in the bottom right corner of the photo.</p>