



DEPARTMENT OF THE ARMY **ENTERED**
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1741 MARSHALL ROAD
FORT BLISS, TEXAS 79916



DEC 15 2016

Directorate of Public Works

Mr. David Cobrain
Project Leader
New Mexico Environmental Department-HWB
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505-6303

Dear Mr. Cobrain:

On June 01, 2016, the Fort Bliss Directorate of Public Works, Environmental Division (DPW-ED) conducted the annual post-closure site inspection of the Dona Ana Range Camp Sanitary Landfill, Solid Waste Management Unit (SWMU) 29/FTBL-011. The inspection was conducted in accordance with the requirements stated in the New Mexico Environmental Department (NMED) Hazardous Waste Bureau letter, dated May 27, 2008.

The NMED correspondence indicated that an annual inspection of the run-on controls and landfill cover be conducted and photographs be provided. During the inspection, the landfill cover, run-on controls, vegetative layer, perimeter fence and warning signs were found to be in good condition (Enclosure 1).

If you have any questions concerning this report, please contact Mr. Ronald Baca, Environmental Division, Directorate of Public Works, at (915) 568-7979 or ronald.h.baca.civ@mail.mil.

Sincerely,

Vicki G. Hamilton, R.A.
Chief, Environmental Division
Directorate of Public Works

Enclosure

Dona Ana Range Camp Sanitary Landfill - Inspection

SWMU-29/FTBL-011

Unit: IMBL- PWE

Inspector: Victor Garcia

Facility ID: SWMU-29/FTBL-11

Telephone Number: (915) 568-5205

Facility Name: Dona Ana Range Camp Sanitary Landfill

Email: victor.h.garcia22.ctr@mail.mil

Inspection Date: June 1, 2016

List of Observations:

1. The landfill cap was uniform and in good condition. There was no evidence of erosion or depressions on the cap's surface.
2. The vegetative layer was in good condition on the landfill cap and areas in the immediate vicinity within the fenced property.
3. The site perimeter fence and warning signs remain in good condition. There were no locations that required maintenance or repairs.

Inspection photographs

Photograph No. 1

View of landfill cap facing North.

No signs of erosion or depressions on landfill cap.
Vegetative layer was in good condition.



**Dona Ana Range Camp Sanitary Landfill - Inspection
SWMU-29/FTBL-011**

Photograph No.2

View of landfill cap facing East.

No signs of erosion or depressions on landfill cap.
Vegetative layer was in good condition.



Photograph No. 3

View of landfill cap facing South.

No signs of erosion or depressions on landfill cap.
Vegetative layer was in good condition.



Dona Ana Range Camp Sanitary Landfill - Inspection SWMU-29/FTBL-011

Photograph No. 4

View of landfill cap facing West.

No signs of erosion or depressions on landfill cap.
Vegetative layer was in good condition.



Photograph No. 5

View of Eastern fence facing South.

Site perimeter fence and warning signs were in good condition.



**Dona Ana Range Camp Sanitary Landfill - Inspection
SWMU-29/FTBL-011**

Photograph No. 6

View of Northern fence facing West.

Site perimeter fence and warning signs were in good condition.



Photograph No. 7

Drainage structure facing Northwest.

