



SUSANA MARTINEZ
Governor
JOHN A. SANCHEZ
Lieutenant Governor

State of New Mexico
ENVIRONMENT DEPARTMENT

Hazardous Waste Bureau

2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6313
Phone (505) 476-6000 Fax (505) 476-6030
www.env.nm.gov



BUTCH TONGATE
Cabinet Secretary
J. C. BORREGO
Deputy Secretary

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

November 2, 2017

Mark Patterson
BRAC Environmental Coordinator
Fort Wingate Depot Activity
13497 Elton Road
North Lima, OH 44452

Steve Smith
USACE
CESWF-PER-DD
819 Taylor Street, Room 3B06
Fort Worth, TX 76102

**RE: CLARIFICATION REGARDING THE PARCEL 3 HAZARDOUS WASTE
MANAGEMENT UNIT CLEANUP OF SOIL CONTAMINATION OUTSIDE OF
THE UNIT BOUNDARY
FORT WINGATE DEPOT ACTIVITY
MCKINLEY COUNTY, NEW MEXICO
EPA ID# NM6213820974
HWB-FWDA-17-001**

Dear Messrs. Patterson and Smith:

The New Mexico Environment Department (NMED) discussed soil sampling and cleanup during a phone conversation that took place on September 22, 2017 between Mark Patterson (BRAC Coordinator), Steve Smith (USACE), and NMED regarding Parcel 3 remediation activity. NMED understands that the Permittee's contractor responsible for removal of contaminated soils at the Hazardous Waste Management Unit (HWMU) may encounter contaminated soils near or beyond the boundary of the HWMU. In lieu of discontinuing excavation activities, backfilling the excavation, and then returning to the site at a later date to re-excavate these contaminated soils, the contractor may elect, in coordination with the Permittee, to remove contaminated soils that extend beyond the HWMU boundary.

NMED agrees that the conditions, sampling protocols, and cleanup criteria stated in the Permittee's NMED-approved December 19, 2012 Final Removal Work Plan, HWMU, Parcel 3,

Messrs. Patterson and Smith


November 2, 2017

Page 2

Revision 1, including all modifications provided in NMED's January 24, 2013 Approval with Modifications letter, apply to the removal of contaminated soils within, below, and adjacent to the HWMU boundary within the inner fence area.

Should you have any questions, please contact Ben Wear of my staff at (505) 476-6041.

Sincerely,



John E. Kieling

Chief

Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
B. Wear, NMED HWB
C. Hendrickson, U.S. EPA Region 6
L. Rodgers, Navajo Nation
S. Begay-Platero, Navajo Nation
M. Harrington, Pueblo of Zuni
C. Seoutewa, Southwest Region BIA
G. Padilla, Navajo BIA
J. Wilson, BIA
B. Howerton, BIA
R. White, BIA
C. Esler, Sundance Consulting, Inc.

File: FWDA 2017 and Reading, Parcel 3, FWDA-17-001