



DEPARTMENT OF THE AIR FORCE

HEADQUARTERS 1606TH AIR BASE WING (MAC)
KIRTLAND AIR FORCE BASE, NEW MEXICO 87117-5000

File KAFB
91 BLU

ENTERED



12 APR 1991

Mr Rich Mayer
Hazardous Waste Management Division
EPA-Region 6
1445 Ross Avenue
Dallas TX 75202-2733

Dear Mr Mayer

We have received the final analytical results from the second round of sampling of our groundwater monitor wells. The first round showed concentrations of 0.99 ug/L (0.79 ug/L second column) of 1,2-Dichloroethane and 1.2 ug/L (1.1 ug/L second column) of Trichloroethene (Trichloroethylene) from well KAFB0902 located approximately 1500 feet southwest of landfill #1.

The second sampling has confirmed the initial detection of contaminants by showing concentrations of 0.59 ug/L (0.62 second column) of 1,2 - Dichloroethane and 0.96 ug/L (0.86 second column) of Trichloroethene.

Well KAFB0902 will continue to be sampled for these constituents. In addition, we will be installing four more groundwater monitoring wells (a fifth is already in-place) at the margins of Landfill 1 in an effort to determine if this landfill could be the source of the contamination.

If you have any questions, please contact Mr John Gould at (505) 846-2773.

Respectfully

James A. Martinez
JAMES A. MARTINES, Colonel, USAF
Director
Environmental Management Division

cc: NMED (Bruce Swanton)

