




UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
 REGION 6  
 1445 ROSS AVENUE, SUITE 1200  
 DALLAS, TX 75202-2733



*Ron K. [unclear]*  
*[unclear]*  
*Steve P. [unclear]*

SEP 28 1994

OCT 4 1994

Scott E. Streifert, Major, Director  
 Environmental Management Division  
 377 ABW/EM  
 2000 Wyoming Boulevard SE  
 Kirtland Air Force Base, NM 87117-5659

Dear Major Streifert:

The Environmental Protection Agency (EPA) has reviewed your SWMU Assessment Report for WP-58, the Laundry Facility, and determined that the facility is a SWMU and should be added to the Kirtland Air Force Base (Kirtland) RCRA/HSWA Permit. Kirtland shall initiate a Class 1 permit modification within 90 days of receipt of this letter to add the Laundry Facility to Appendix V of their permit.

A site-specific sampling plan for the Laundry Facility shall be submitted to the EPA within 60 days of receipt of this letter. Please note that the EPA is not requiring a separate RCRA Facility Investigation (RFI) Work Plan for this SWMU. Instead, the investigation shall be conducted in accordance with the Health and Safety Plan, Project Management Plan, and Data Collection Quality Assurance Plan approved on April 7, 1994 for the investigation of the Appendix III SWMUs.

Please contact Nancy Morlock of my staff at (214) 665-6650 if you have any questions.

Sincerely yours,

*William K. Honker*  
 William K. Honker, P.E., Chief  
 RCRA Permits Branch



Mr. Steve Pullen  
 Hazardous and Radioactive Materials Bureau  
 New Mexico Environment Department

KAFB1508



r that