



REPLY TO
ATTENTION OF

DEPARTMENT OF THE ARMY ENTERED
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1 PERSHING ROAD
FORT BLISS, TEXAS 79916-3803



December 17, 2009

Environmental Division

Mr. David Cobrain
Project Leader
New Mexico Environmental Department-HWB
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303

Dear Mr. Cobrain:

On October 15, 2009 the Directorate of Public Works, Environmental Division conducted the annual Post-Closure Site Inspection of the McGregor Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 18/FTBL-013 per NMED letter dated June 12, 2007. The correspondence indicated that the following information must be included in the site inspection; observations of the cover i.e. cap, drainage system, and vegetation and submit photographs and descriptions of the site to NMED.

The cover of SWMU-18 is in very good condition. Vegetation has begun to spread throughout the landfill cover and the vegetation along the edges of the cover and drainage system are extremely robust.

Prior to Ms. Cheryl Frischkorn leaving NMED, Fort Bliss asked to move a portion of the fence at SWMU-18 approximately (30) thirty feet, to place a security fence around the perimeter of the McGregor Range Cantonment. Ms. Frischkorn approved the relocation of the fence as long as the rubble in SWMU-18 was not disturbed. Approximately 200 feet of fence was replaced on the northern portion of SWMU-18, and the rubble within the landfill has not been disturbed. There is now a dirt trail between SWMU-18 and the perimeter of the cantonment used for security vehicles to patrol the perimeter of the cantonment

If you have any questions concerning this report please do not hesitate to contact Ron Baca, at (915) 568-7979, or email Mr. Baca at the following address ron.baca@us.army.mil.

Sincerely,

for Sylvia D. Waggoner
Keith Landreth
Chief, Environmental Division
Directorate of Public Works

Enclosures

ENVIRONMENTAL PERFORMANCE ASSESSMENT

IMSW-BLS-DPW-E

01 December 2009

MEMORANDUM FOR (Program Manager), ATTN: Mr. Ron Baca

SUBJECT: DPW- Environment Division EPAS Inspection.

1. On 15 October 2009, the DPW- Environment Division Environmental Performance Assessment System (EPAS) team conducted the annual compliance audit of Fort Bliss Solid Waste Management Units (SWMU) 18, (SWMU) 27 and (SWMU) 29. The attached report lists findings of noncompliance, corrective actions, and regulatory references.
2. If you have questions/comments regarding this report, please contact Isaac Trejo, DPW-E Division, 569-6297, or myself at 568-3782.

Sylvia Q. Waggoner
for KEITH LANDRETH, CHIEF
DPW-Environmental Division

ENVIRONMENTAL PERFORMANCE ASSESSMENT

Facility ID: FTBL-13

Facility Name: SWMU-18

P.O.C: Ron Baca

Telephone Number: 568-7979

Assessor: Isaac Trejo

Telephone Number: 569-6297

LIST OF OBSERVATIONS:

1. Observation: Fence broken along the North East to North West boundary, approximately 300 feet.

Corrective Action: Repaired broken fence on 10-23-2009

2. Positive Observation: Erosion was not found at this landfill.

3. Positive Observation: Vegetation is very healthy on the surrounding area of the landfill and on the final cover.

Observation 1. Missing Fence	Fence broken along the North East to North West boundary, approximately 300 feet.
	

1. Repaired fence	Repaired broken fence on 10-23-2009
	

Observations	
---------------------	--

ENVIRONMENTAL PERFORMANCE ASSESSMENT

2 & 3

