



SUSANA MARTINEZ
Governor
JOHN A. SANCHEZ
Lieutenant Governor

NEW MEXICO
ENVIRONMENT DEPARTMENT

ENTERED



2905 Rodeo Park Drive East, Building 1,
Santa Fe, NM 87505-6303
Phone (505)476-6000 Fax (505) 476-6030
www.nmenv.state.nm.us

RYAN FLYNN
Cabinet Secretary
BUTCH TONGATE
Deputy Secretary

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

July 1, 2014

Vicki G. Hamilton, R.A.
Chief, Environmental Division
Directorate of Public Works
Department of the Army
Headquarters, U.S. Army Garrison Command
1741 Marshall Road
Fort Bliss, TX 79916-3803

**RE: REVIEW
ANNUAL POST-CLOSURE SITE INSPECTION REPORT
MCGREGOR RANGE CAMP LANDFILL, SWMU 18/FTBL-013
FORT BLISS, NEW MEXICO
EPA ID #NM4213720101
HWB-FB-14-001**

Dear Ms. Hamilton:

The New Mexico Environment Department (NMED) has reviewed the Department of Army's (Permittee) *Annual Post-Closure Site Inspection of the Closed McGregor Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 18/FTBL-013*, Fort Bliss, New Mexico (Report), dated January 2, 2014 and received January 8, 2014.

In accordance with NMED's *Approval of Post-Closure Certification Report for McGregor Range Camp Landfill (Solid Waste Management Unit No. 18), Fort Bliss, New Mexico* (June 12, 2007), the Permittee conducted an inspection of the site on May 30, 2013, and found it to be in good condition. Evidence of minor erosion was observed at the southern boundary of the site but not found to affect the cover of the landfill. Healthy vegetation growth was observed throughout the landfill cover and in and around the drainage system. Signage was inspected and was determined to be in good condition. The fence in the southern portion of the unit was retightened.


Ms. Hamilton
July 1, 2014
Page 2

The Permittee has fulfilled its obligation to conduct the annual site inspection and submit an annual report to NMED. The Permittee must continue to conduct annual inspections at SWMU 18 and submit a report to NMED documenting results of the inspection.

As previously requested by NMED in the document *Review Annual Post-Closure Site Inspection Report for Dona Ana Rubble Pit Landfill, SWMU 18/FTBL-012* dated April 8, 2013 the inspection report must also include an approximate distance between the cap and any erosional features. The inspection report for next year is due no later than December 31, 2014.

Please contact Siona Briley at (505) 476-6049 if you have any questions regarding this letter.

Sincerely,



John E. Kieling
Chief
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
N. Dhawan, NMED HWB
S. Briley, NMED HWB
V. Hamilton, DoA, Ft. Bliss

File: Ft. Bliss (SWMU 18) Annual Site Inspection Report
FB-14-001