



SUSANA MARTINEZ
Governor

JOHN A. SANCHEZ
Lt. Governor

NEW MEXICO 
ENVIRONMENT DEPARTMENT

2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6313
Phone (505) 476-6000 Fax (505) 476-6030
www.env.nm.gov



BUTCH TONGATE
Cabinet Secretary

J. C. BORREGO
Deputy Secretary

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

April 14, 2017

Sylvia Waggoner
Chief, Compliance Branch
US Army Fort Bliss Garrison
DPW-Environmental Division
Building 622, Taylor Road
Fort Bliss, TX 79916-3803

**RE: REVIEW
ANNUAL POST-CLOSURE SITE INSPECTION REPORT
MCGREGOR RANGE CAMP LANDFILL, SWMU 18/FTBL-013
FORT BLISS, NEW MEXICO
EPA ID #NM4213720101
HWB-FB-16-003**

Dear Ms. Waggoner:

The New Mexico Environment Department (NMED) has reviewed the Department of Army (Permittee) *Annual Post-Closure Site Inspection of the Closed McGregor Range Camp Landfill, Solid Waste Management Unit (SWMU) 18/FTBL-013*, Fort Bliss, New Mexico (Report), dated December 15, 2016, and received December 19, 2016.

In accordance with NMED's *Approval of Post-Closure Certification Report for McGregor Range Camp Landfill (Solid Waste Management Unit No. 18), Fort Bliss, New Mexico* (June 12, 2007), the Permittee conducted an inspection of the site on June 1, 2016, and found it to be in good condition. No evidence of erosion was observed and healthy vegetation growth was observed throughout the landfill cover and in and around the drainage system. The site perimeter fence and signage was inspected and was determined to be in good condition.


The Permittee has fulfilled its obligation to conduct the annual site inspection and submit an annual report to NMED. The Permittee must continue to conduct the annual inspection at SWMU 18 and submit the associated report to NMED documenting results of the inspection.

Ms. Waggoner
April 14, 2017
Page 2

The inspection report for 2017 is due no later than **December 31, 2017**.

Please contact Aubrey Pierce at (505) 476-6058 if you have any questions regarding this letter.

Sincerely,



John E. Kieling
Chief
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
K. VanHorn, NMED HWB
A. Pierce, NMED HWB
L. King, EPA, Region 6 (6MM-RC)

File: 2016 Ft. Bliss (SWMU 18) Annual Site Inspection Report
WHB-FB-16-003