



SUSANA MARTINEZ
Governor
JOHN A. SANCHEZ
Lieutenant Governor

State of New Mexico **ENTERED**
ENVIRONMENT DEPARTMENT
Hazardous Waste Bureau

2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6313
Phone (505) 476-6000 Fax (505) 476-6030
www.env.nm.gov



BUTCH TONGATE
Cabinet Secretary
J. C. BORREGO
Deputy Secretary

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

February 8, 2018

Sylvia A. Waggoner
Chief, Compliance Branch
US Army Fort Bliss Garrison
DPW-Environmental Division
Building 622, Taylor Road
Fort Bliss, TX 79916-3803

**RE: REVIEW
ANNUAL POST-CLOSURE SITE INSPECTION REPORT
MCGREGOR RANGE CAMP LANDFILL
SWMU 18/FTBL-013
FORT BLISS, NEW MEXICO
EPA ID #NM4213720101
HWB-FB-17-003**

Dear Ms. Waggoner:

The New Mexico Environment Department (NMED) has reviewed the Department of Army (Permittee) *Annual Post-Closure Site Inspection Report, Fort Bliss Site No. 13 (FTBL-013)/Solid Waste Management Unit 18 (SWMU-18) McGregor Range Camp Landfill Fort Bliss, New Mexico*, dated December 14, 2017 and received December 20, 2017.

In accordance with NMED's *Approval of Post-Closure Certification Report for McGregor Range Camp Landfill (Solid Waste Management Unit No. 18), Fort Bliss, New Mexico*, dated June 12, 2007, the Permittee conducted an inspection of the site on June 7, 2017, and found the landfill cover, drainage system, site perimeter fence, and signage to be in good condition.


The Permittee has fulfilled its obligation to conduct the annual site inspection and submit an annual report to NMED. The Permittee must continue to conduct annual inspections at SWMU 18 and submit the associated report to NMED documenting results of the

Ms. Waggoner
February 8, 2018
Page 2

inspection. The inspection report for next year is due no later than **December 31, 2018**.

If you have any questions regarding this letter, please contact Michiya Suzuki (505) 476-6059.

Sincerely,

A handwritten signature in black ink, appearing to read 'John E. Kieling', written over a horizontal line.

John E. Kieling
Chief
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
K. VanHorn, NMED HWB
M. Suzuki, NMED HWB
L. King, EPA, Region 6 (6MM-RC)

File: 2017 Ft. Bliss (SWMU 18) Annual Site Inspection Report
HWB-FB-17-003