



NEW MEXICO ENTERED
ENVIRONMENT DEPARTMENT



Hazardous Waste Bureau

2905 Rodeo Park Drive East, Building 1

Santa Fe, New Mexico 87505-6313

Phone (505) 476-6000 Fax (505) 476-6030

www.env.nm.gov

MICHELLE LUJAN GRISHAM
Governor

HOWIE C. MORALES
Lt. Governor

JAMES C. KENNEY
Cabinet Secretary Designate

JENNIFER J. PRUETT
Deputy Secretary

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

February 7, 2019

Jesus D. Moncada
Chief, Compliance Branch
US Army Fort Bliss Garrison
DPW-Environmental Division
Building 622, Taylor Road
Fort Bliss, TX 79916-3803

RE: REVIEW
ANNUAL POST-CLOSURE SITE INSPECTION REPORT
FORT BLISS SITE NO. 11 (FTBL-011)/SOLID WASTE MANAGEMENT
UNIT 29 (SWMU-29)
DOÑA ANA RANGE CAMP SANITARY LANDFILL
FORT BLISS, NEW MEXICO
EPA ID #NM4213720101
HWB-FB-18-005

Dear Mr. Moncada:

The New Mexico Environment Department (NMED) has reviewed the Department of Army (Permittee) *Annual Post-Closure Site Inspection Report, Fort Bliss Site No. 11 (FTBL-011)/Solid Waste Management Unit 29 (SWMU-29) Doña Ana Range Camp Sanitary Landfill Fort Bliss, New Mexico* (Report), dated December 21, 2018 and received December 31, 2018.

In accordance with NMED's *Approval of FTBL-11/SWMU-29 Adjacent Run-on Controls, Doña Ana Range Camp, Fort Bliss, New Mexico*, dated May 27, 2008, the Permittee conducted an inspection of the site on October 24, 2018 and found the landfill cover, vegetative layer, and perimeter fence and warning signs to be in good condition.


The Permittee has fulfilled its obligation to conduct the annual site inspection and submit an annual report to NMED. The Permittee must continue to conduct annual inspections

Mr. Moncada
February 7, 2019
Page 2

at SWMU 29 and submit the associated report to NMED documenting results of the inspection. The 2019 inspection report is due no later than **December 31, 2019**.

If you have any questions regarding this letter, please contact Michiya Suzuki (505) 476-6059.

Sincerely,



John E. Kieling
Chief
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
K. VanHorn, NMED HWB
M. Suzuki, NMED HWB
L. King, EPA, Region 6 (6MM-RC)

File: 2018 Ft. Bliss (SWMU 29) Site Inspection Report