




DEPARTMENT OF THE AIR FORCE
HEADQUARTERS 377TH AIR BASE WING (AFMC)

ENTIRED

377 ABW/EMR
2000 Wyoming Blvd SE
Kirtland AFB NM 87117-5659

Mr. Stephen Pullen, DSMOA
Hazardous and Radioactive Materials Bureau
New Mexico Environment Department
525 Camino de los Marquez, Ste 4
Santa Fe NM 87502



9 March 1995

Dear Mr. Pullen

Based on recently received test results that indicate high levels of lead in the slag piles, we revised the relative risk evaluation worksheet for RW-68 from medium to high risk. The revised worksheet is attached.

Please contact Mr. Jerry Sillerud, (505) 846-2773/0053, if you have any questions.

Sincerely

Christopher B. DeWitt
CHRISTOPHER B. DeWITT, R.P.G
Chief, Restoration Branch
Environmental Management Division

Attachment:
Worksheet

KAFB1585

