



File SPIC A - 200



May 18, 1992

Dr. Herb Grover
Permit Group Coordinator
New Mexico Environment Division
Hazardous and Radioactive Materials Division
Harold Runnels Building
1190 St. Francis Drive
Santa Fe, NM 87502

RE: Safety-Kleen Corp.
2720 Girard NE
Albuquerque, NM 87107
EPA I.D. NMD000804294

Dear Dr. Grover:

Enclosed are two copies of an Interim Status Partial Facility Closure Plan for the above-referenced Safety-Kleen Corp. Service Center. The plan describes procedures to close the old underground storage tanks and return/fill station.

If you have any questions or comments concerning the information contained in the Closure Plan, please feel free to contact Jack Bedessem of TriHydro Corporation at (307) 745-7474, or me at (310) 831-3903.

Sincerely,
SAFETY-KLEEN CORP.

Anne Lunt

Anne Lunt *ALB*
Sr. Project Manager - Remediation

cc: Mr. Allyn Davis
Director
Hazardous Waste Management Division
USEPA - Region 6
1445 Ross Avenue
Suite 1200
Dallas, TX 75202-2733

Gary Long/Safety-Kleen Elgin

Ralph Ondatje/Safety-Kleen Albuquerque

*Enclosure
not
found*