

MONTHLY PROGRESS REPORT For month ending July 31th, 2018

CV-97-0206 (D.N.M) Albuquerque v. Sparton Technology, Inc.

08/07/2018

Tasks Completed:

- A. Groundwater Monitoring Plan
 - Began preparing for the 3Q2018 Ground Water Measurement and Sampling event

- B. Public Involvement Plan
 - None

- C. Deep Flow Zone System
 - None

- D. Assessment of Aquifer Restoration
 - Completed the preparation of the CY2017 Annual Report, and transmitted the report to the Agencies on July 13, 2018.

- E. Offsite-Containment System (CW-1)
 - The system ran 98.53% of the time and pumped 13,298,052 gallons (an average of 297.9 gpm). There was 1 unscheduled shutdown:
 - o On 07/05/18 for 10.95 hours due to a power outage.
 - Collected the monthly influent and effluent samples and measured the water level in the infiltration gallery piezometer.
 - Filed the monthly discharge report with the Office of the State Engineer as required under Permit-RG-69659.
 - The Aqua-Mag tank was replenished twice:
 - o On 07/16/18 with 27.05 gallons
 - o On 07/30/18 with 21.58 gallons

- F. Source Containment System (CW-2)
 - The system ran 99.95% of the time and pumped 2,817,314 gallons (an average of 63.1 gpm). There was 1 scheduled shutdown:
 - o On 07/16/18 for 22 minutes due to a Tank Exchange.
 - Filed the monthly discharge report with the Office of the State Engineer as required under Permit-RG-73531.
 - Collected the monthly influent and effluent samples from the treatment system.



EA Engineering, Science,
and Technology, Inc., PBC

- Continued to operate the chromium removal unit during the entire month and route 27 gpm of the pumped water through the unit and blended with the remainder of the pumped water to meet the New Mexico Water Quality Control Commission chromium standard of 0.050 mg/L in the effluent discharged into the ponds.
- Replaced the first tank of the chromium removal unit on 07/16/18. Following the modification of the tank exchange frequency to occur every four weeks, no exceedance of the NMWQS in the effluent from the air-stripper was observed.
- Replaced the pretreatment filter for the Chromium Exchange Tanks on 07/14/18.
- Prior to each Tank Exchange collected chromium samples of (a) the influent to the building; (b) the effluent from the second tank; and (c) the effluent from the air-stripper on tank exchange day.
- The Aqua-Mag Tank was replenished once:
 - o On 07/24/18 with 11.72 gallons

G. Other

- All field activities were performed by EA personnel and subcontractors following standard operating procedures, including health and safety requirements, outlined in the Operation and Maintenance Manuals of the On-Site and Off-Site Containment Systems.

H. Problems Encountered or Anticipated:

- None

Tasks Planned:

I. Groundwater Monitoring Plan

- The 3Q2018 Ground Water Measurement and Sampling event is scheduled to begin on 08/01/18.
- Work will begin on the development of a Work Plan for the Plugging, Abandonment, and Replacement of monitoring well MW-62.

J. Public Involvement Plan

- None

K. Deep Flow Zone System

- None

L. Assessment of Aquifer Restoration

- None

M. Offsite-Containment System

- The monthly influent and effluent samples will be collected, and the water level will be measured in the infiltration gallery piezometer.
- The required discharge report will be filed with the Office of the State Engineer.



EA Engineering, Science,
and Technology, Inc., PBC

N. Source Containment System

- The monthly influent and effluent samples will be collected.
- The required discharge report will be filed with the Office of the State Engineer; and
- Tank Exchange chromium sampling of (a) the influent; (b) the effluent from the second tank; and (c) the effluent from the air-stripper will continue.
- The first tank of the Chromium Removal unit will be replaced on 08/13/18.
- The pretreatment filter will be replaced on an as need basis as pressure rises or flow is reduced in the system.

O. Other

- None

P. Problems Encountered or Anticipated:

- None

By:

Kevin McKeage, E.I.T.
Engineer for EA on behalf of Sparton

Robert Marley, P.G.
Project Manager for EA on behalf of Sparton.

Cc: Mr. Chuck Hendrickson (EPA: 214-665-7263)
Mr. Dave Cobrain (NMED: 505-476-6030)

07 August 2018

Mr. Charles Palmer
Office of the State Engineer
5550 San Antonio Dr. NE
Albuquerque, New Mexico
Dist1.meterreadings@state.nm.us

RE: Permit RG-69659, RG-73531T

Dear Mr. Palmer:

Below is the meter report for the month of June 2018. A total of 13,298,052 gallons were treated by the air stripper at CW-1 and discharged via underground pipeline to the infiltration Gallery located in the Calabacillas Arroyo. A total of 2,817,314 gallons were treated by the air stripper at CW-2 and discharged into rapid infiltration pond 2 located northwest of the CW-2 Stripper building.

Date	CW-1		CW-2	
	Meter Reading	Discharge	Meter Reading	Discharge
01/01/2018	139,018,030		20,935,349	
02/01/2018	152,593,682	13,575,652	22,608,190	1,672,841
03/01/2018	164,866,071	12,272,389	24,278,887	1,670,697
04/01/2018	178,356,195	13,490,124	27,113,170	2,834,283
05/01/2018	191,457,579	13,101,384	27,716,577	603,407
06/01/2018	204,967,628	13,510,049	30,583,253	2,866,676
07/01/2018	218,025,179	13,057,551	33,355,272	2,772,019
08/01/2018	231,323,231	13,298,052	36,172,586	2,817,314
Total (YTD)		92,305,201		15,237,237

Thank you,

EA ENGINEERING, SCIENCE,
AND TECHNOLOGY, INC., PBC

Kevin McKeage, E.I.T.
Engineer

cc: Robert Marley, P.G.
Vener Mustafin, P.E.