


12-31-2010

ENTERED




Aeration Basin with Benzene Stripper in background (photo taken 2008)





East Fuel Loading Rack with Hot Oil Tank Farm in Background (photo taken 2010)






Unknown location (photo taken 2005)

2005 10 26





Machine Shop (?) photo take 2005

2005 10 26






Machine Shop Maintenance Area (?) photo taken 2005

2005 10 26






Cracked concrete and hydrocarbon staining outside of secondary containment

2005 10 26






Flare and tanks to left of OAPIS photo taken 2007 site visit

12 1:57PM





Hydrocarbon staining