

8-10-14



PHOTOS FROM EPA INSPECTION AUGUST 2014
(EPA INSPECTION REPORT NOT FINALIZED
FOR INFORMATION PURPOSES ONLY)

NMED



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 9

Location: Western Refining - Gallup Refinery, 92 Giant Crossing Road		
City: Gallup	County: McKinley County	State: New Mexico



Photo File Name: P8120009

Date of Photo: 12 August 2014

Time of Photo: 1021

Photographer: Wm. Mansfield

Description: WWTP Filter-Cake Press' roll-off box sitting outside of secondary containment. Noted some spillage on the ground, under and next to the roll-off box.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Photograph Log

Photo No. 21

Location: Western Refining - Gallup Refinery, 92 Giant Crossing Road		
City: Gallup	County: McKinley County	State: New Mexico



Photo File Name: P8120021

Date of Photo: 12 August 2014

Time of Photo: 1115

Photographer: Wm. Mansfield

Description: 90-Day hazardous waste storage yard with leaking drum, labeled as "Hazardous Waste, Accumulation Start Date: 07-11-14, Contents: Iron Chelate". Other drums exceeded the 90 day storage limit (see Charles Barnes inspection photos).



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Photograph Log

Photo No. 6

Location: Western Refining - Gallup Refinery, 92 Giant Crossing Road		
City: Gallup	County: McKinley County	State: New Mexico




Photo File Name: 2141 Date

of Photo: 08/12/2014

Time of Photo: 1107

Photographer: Charles Barnes

Description: Pond 1 and Evaporation ponds – Pink color noted.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Photograph Log

Photo No. 10

Location: Western Refining - Gallup Refinery, 92 Giant Crossing Road

City: Gallup

County: McKinley County

State: New Mexico



Photo File Name: P8120010

Date of Photo: 12 August 2014

Time of Photo: 1025

Photographer: Wm. Mansfield

Description: WWTP - Baker tanks used as grit tanks to stored wastewater from the float tank. Inadequate secondary containment. It was also noted during the inspection that the tanks had an approximate 0.4-0.5 mile release on August 5, 2014.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Photograph Log

Photo No. 19

Location: Western Refining - Gallup Refinery, 92 Giant Crossing Road		
City: Gallup	County: McKinley County	State: New Mexico



Photo File Name: 2154 Date
of Photo: 08/12/2014
Time of Photo: 1507
Photographer: Charles Barnes
Description: Seep Site



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 22

Location: Western Refining - Gallup Refinery, 92 Giant Crossing Road		
City: Gallup	County: McKinley County	State: New Mexico




Photo File Name: P8120022

Date of Photo: 12 August 2014

Time of Photo: 1425

Photographer: Wm. Mansfield

Description: SWMU-22 - Additive Tank Farm. Noted weak seal joints on the concrete floor of the secondary containment.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 30

Location: Western Refining - Gallup Refinery, 92 Giant Crossing Road		
City: Gallup	County: McKinley County	State: New Mexico




Photo File Name: P8120030

Date of Photo: 12 August 2014

Time of Photo: 1602

Photographer: Wm. Mansfield

Description: Diesel tank @ Fire Training Area. Noted liquid seeping through secondary containment. Strong e diesel odor noted with soils affected.